



July 1, 2019

At the Board's request, the area of Turkey Creek within the District's jurisdiction was inspected to identify potential capital projects for the **2020 Capital Improvements Plan**. Based on that inspection, the following list of items was identified. The cost information was based on the most recent work performed by Max Rieke & Bros. for the drainage district.

Engineer's Opinion of Probable Cost - Turkey Creek Maintenance

Area	Description	UNIT	UNIT PRICE	QUANTITY	Cost
A	HOLE REPAIR	EA	\$500.00	1	\$500.00
B	HOLE REPAIR	EA	\$500.00	1	\$500.00
C	UNDER-MINING	LF	\$125.00	150	\$18,750.00
D	HOLE REPAIR	EA	\$500.00	1	\$500.00
E	HOLE REPAIR	EA	\$500.00	1	\$500.00
F	REPAIR WALL	LF	\$500.00	100	\$50,000
G	PLANTING MAINTENANCE	EA	\$1,500	1	\$1,500
H	HOLE REPAIR	EA	\$500.00	3	\$1,500.00
I	REPAIR WALL	EA	\$500.00	220	\$110,000
TOTAL					\$ 183,750



A – HOLE REPAIR - \$500



B – HOLE REPAIR - \$500



C – UNDERMINING - \$18,750



D – HOLE REPAIR - \$500



E – HOLE REPAIR - \$500



F – REPAIR WALL - \$50,000



G – PLANTING MAINTENANCE - \$1,500



H – HOLE REPAIRS - \$1,500



I – REPAIR WALL - \$110,000